



JON M. HUNTSMAN, JR.
Governor

GARY R. HERBERT
Lieutenant Governor

State of Utah

DEPARTMENT OF NATURAL RESOURCES

Division of Oil, Gas & Mining

MICHAEL R. STYLER
Executive Director

JOHN R. BAZA
Division Director

Inspection Report

Minerals Regulatory Program

October 10, 2006

Supervisor 

Mine Name: Manning Canyon
Operator Name: Interstate Brick Company

Permit number: M0490036
Inspection Date: August 22, 2006
Time: 10:30 am

Inspector(s): Lynn Kunzler, DOGM
Other Participants: John Hewitt

Mine Status: Inactive

Elements of Inspection	Evaluated	Comment	Enforcement
1. Permits, Revisions, Transfer, Bonds	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
2. Public Safety (shafts, adits, trash, signs, highwalls)	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
3. Protection of Drainages / Erosion Control	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
4. Deleterious Material	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
5. Roads (maintenance, surfacing, dust control, safety)	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
6. Concurrent Reclamation	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
7. Backfilling/Grading (trenches, pits, roads,	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
8. Soils	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
9. Revegetation	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
10. Other	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>

Purpose of Inspection:
Routine inspection while in the area.


Inspection Summary:
This site was permitted in 2000. The last active mining was done in 2001. The operator indicated that they are planning to mine again next year. Approximately 5 acres have been disturbed. The operator will need to provide a surety for this site by December 8, 2006

There were no garbage or erosion problems noted, The site appeared stable and well maintained.

Note: There is historic disturbances in the area, the operator was advised to make sure this was documented in his permit so that he would not be held accountable for reclamation

Photos were taken of this site.

Conclusions and Recommendations:
Continue to monitor this site while in the area. Operator was advised that the surety for this site would follow the Division's average cost per acre - amount needed is \$18,600.

Inspector's Signature 

LK:pb

O:\M049-Utah\S0490036-ManningCyn\inspections\insp-08222006.doc

Date: October 10, 2006